Work Orde August 12, 2009	er ID 51251 4:17:22 PM										Page
Revision ID: Item Name: Start Date: Required Date:	D2221-7 H Rib  08/12/2009 Start Qty: 4.4 08/18/2009 Req'd Qty: 4.4	1 (BB)((B)E) (BA)	Accept	Cust Item II Customer:	<b>                                     </b>		<b>     </b>    5	Setup	Start Stop	***************************************	
Reference:	Process Plan:	Date: <u>09-08 /</u>	る Tooling: SPC (Y/N):	Da			Į	Run	Start Stop		
Sequence ID/ Work Center II	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr D2221	Revision Nbr Rev H										
100 	Large Fab Memo 1- Cut	as per dwg D2221 □2- Deburr a	0.00 0.00 und remove identification	SAN ESS SAN ESS n markings on tube	<b>6</b> ~ 1 7:		<u> </u>				-
110 QC Quality Control	QC5- Inspect part	completeness to step on W/O	0.00	5 05/08/17			(F)	9	6		
				٨.							

120

Memo

Identify as per dwg & Stock Location: 325kel

0.00

109.08-17

Packaging

0.00

Packaging

Dart Aerospace Ltd	D	art	Ae	ros	ba	ce	Ltd
--------------------	---	-----	----	-----	----	----	-----

- Dan Ac	ТОРИОС											
W/O:			W	WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CHA	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									-			
Part No	:	PAR #:	Fault Cate	Fault Category: NCR: Yes No					o DQA: Date:			
Resolution:			Dispositio	on:	QA: N	/C Clos	sed:		Date: _			
NCR:		1	WORK ORD	ER NON-CONFORMA	ANCE (I	VCR)						
DATE	CTED	Description of NG			ion B		Verifi	cation	Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date		ion C	Chief Eng	QC Inspector		

NOTE: Date & initial all entries

## Work Order ID 51251

Н



Page 2

August 12, 2009 4:17:22 PM

**Required Date:** 08/18/2009

Item ID:

D2221-7

Accept



Setup Start

Stop



**Revision ID:** 

Rib Item Name:

**Start Date:** 08/12/2009 Start Qty: 4.00

Operation

Description

Req'd Qty: 4.00



**Cust Item ID: Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Draw

Run Start

QC:

Date:

SPC (Y/N):

Set Up/

Date:

Reject

Stop

Insp.

Sequence ID/

Work Center ID

QC21- Final Inspection - Work Order Release

**Run Hours** 0.00

Number Rev.

Draw

Accept Plan Qty Code

Qty

Reject Number Stamp

130

Memo

0.00

Mf 69-08-17

Quality Control

<b>~</b>	•		
1 12T	AAra	chara	1 1/4
vait	7010	space	Llu

		<del></del>									
W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
1			V3.0								
Part No	:	PAR #:	Fault Category:			No <b>DQ</b>	<b>A</b> :	Date:			
	Res	solution:	Disposition	:	QA: N/C C	losed:		Date: _			
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCI	R)	<u>.</u>				
DATE	STEP	Description of NC	Corrective Action Section			Verifi	cation	Approval	Approval		
	0121	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector		

NOTE: Date & initial all entries

August 12, 2009 4:17:22 PM

Work Order ID: 51251

Parent Item:

D2221-7RevH

Parent Item Name: Rib

Comments:



Last

Start Date: 08/12/2009

Required Date: 08/18/2009

Start Qty: 4.00

Required Qty: 4.00

Component Item ID/ Item Name

Item ID

Replacement Mfg/ Purch Bin Primary Item Location

Location

Route Seq ID Unit of Measure Hand

Qty on Remaining

Qty Qty To Pick Issued Date Issued

Status

M304TS0.750W.065

Purchased

No

100

f

1,618.507 19.3861

SAD 09-08-17

204 50	T 7	5 75 OC	EW		


304 SQ Tube .75x.75x.065W	

<u>Warehouse</u>	Loc Qty	Loc Code	
<b>Location</b>			
Main Warehouse			
MAT	6.307103691		
112051	-0.7368363		
112263	7.04394		
Main Warehouse			
WA	1612.1999		
112263	12.1999		
112344	600		14.3861
112398	1000		

Dart Aeros	pace Ltd
------------	----------

Dail Ae	rospace	Liu									
W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				*>							
Part No:		PAR #:	Fault Categ	jory:	NCR: Yes No DQA: Date:						
	Resolution:		Disposition	) <b>:</b>	_ QA: N/C	Closed: _		Date: _			
NCR:			WORK ORDE	R NON-CONFORMA	ANCE (NO	CR)					
		Description of NC		ion B	Vori	fication	Approval	Approval			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	1&   <sub>Se</sub>	Verification Ap Section C Ch		QC Inspector		
			-								
								1			
							<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>		:		
							, <u>.</u>				
						ı		1			

NOTE: Date & initial all entries



## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
				:						
Part No	١•	PAR #· Fault Category:	NCD: Vos	. No <b>DO</b>	۸.	Dato:				

 Resolution: \_\_\_\_\_\_\_ Disposition: \_\_\_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_\_ Date: \_\_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Varification	Approval Chief Eng	Approval QC Inspector				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C						
			:									
				*								
	į.				·							
				<u>, , , , , , , , , , , , , , , , , , , </u>								
	ļ											
				,								
							1					

H:\fFGRMS\Quality Assurance\approved QA\NCRWO RevE

NOTE: Date & initial all entries